

Utah Test and Training Range
Issued February 13, 2003

ATTACHMENT 14
LANDFILL 5 INSPECTION PLAN

LANDFILL 5 INSPECTION PLAN

Due to the remoteness of the Landfill 5 site, inspections by a representative of the Hill AFB Environmental Management Directorate will occur on a monthly basis. An inspection form will be filled out and maintained in the Range Environmental Office. All inspection forms will be kept for a period of at least 5 years. Inspections will continue throughout the entire post-closure period. The inspection form will note the following:

- Date and time of inspection.
- Name of inspector.
- Integrity and effectiveness of the final cover for the following factors:
 - Settling
 - Subsidence
 - Erosion (wind and rain)
 - Vandalism
 - Burrowing rodents
 - Ponding or standing water
- Erosion from run-on and run-off will be checked and corrected as necessary.
- Integrity of the gates, fencing, and groundwater monitoring well heads surrounding the disposal area will be checked for any sign of vandalism or other deterioration.
- Nearest surveyed benchmark (located at the gate to the 100-foot by 50-foot drum storage area at Landfill 5 site) will be inspected for vandalism or other deterioration and will be repaired or resurveyed as necessary.
- Visually inspect signs for fading and/or deterioration.

If any of the mentioned problems are seen during the inspection, they will be so noted on the inspection form. Additionally, these problems will be verbally communicated to the appropriate UDEQ Post-Closure Contact. All problems with Landfill 5 will be resolved within a 72-hour period.